



SHARP®

March 5, 2002

Sharp Display Discontinuation of Duty Display Products:

A) Sharp Driver IC

1) Model

- * LM64C37N
- * LM64C21P
- * LM057QBTT05
- * LM057QB1T04
- * LM6Q401

2) Reason

- * IC Group is planning to discontinue the supply IC for the above LCD due to low activity for long time.

3) Schedule

- * LTB - May 30, 2002
- * Last MP - August 31, 2002

B) Hitachi Driver IC

1) Model

- * LM000014
- * LM09602G



- * LM160011
- * LM19202F
- * LM16X221
- * LM16X22A
- * LM024LB1S02
- * LM16A21
- * LM16A211
- * LM16X21A
- * LM16X21B
- * LM16155
- * LM162A02
- * LM16255
- * LM16255K
- * LM162551
- * LM16257
- * LM20A21
- * LM20X21A
- * LM20255T
- * LM40A21
- * LM40X21A
- * LM40X21B

2) Reason



- * Hitachi is planning to discontinue the IC supply.

3) Schedule

- * LTB - August 30, 2002
- * Last MP - December 27, 2002

Pls. send the LTB PO in on time and thanks for the cooperation.

www.panelook.com